


- Programmer Fuse Setup**
- 1) Brownout Disabled
  - 2) RC Osc 4.8MHz 14ck+64ms

**NOTES:** NO OTHER FUSES SET  
 STK500 Voltage to 4 Volts  
 "VTARGET" Jumper Installed  
 LineBot Power OFF to Program

**SMT Part Identification**

- 2N3904 - "1A"
- BAT54 - "L43"
- 1N914A - "5D"



<b>TIGERBOTICS</b>		
<small>400 Daily Lane P.O. Box 5210 Grants Pass, Oregon (541) 472-8444</small>		
<b>Atmel Tiny13 Line Follower</b>		
File: LINEBOT13.DDB	(C) 2007	07137-100
Date: 07/13/07		